#### Work Order Detail for Asset 233



Work Order: MRDVSH-2020-487 180 DAY Status: OPEN Dept: MECH - MECHANICAL Warranty: NO Asset No: 233 - 1978 PULLMAN/MK BTC-1C COACH Serial No: 233 License: JEFF.FORREST Date In: 05/11/2020 06:27 Asset No: Opened By: Current Equip Status: Date Due: 06/25/2020 06:27 1978-PULLMAN/MK-BTC CUT Eq Type: -1C 257-530001 Opened: 05/11/2020 06:27 Job Type: PM Account: Finished: Meter 1: 0.00 Reference WO: 0.00 Closed: 0.00 Estimated Hours: Meter 2: 0.00 User Hours: 0.00 Warranty Expire: Shop Hrs: **M4 - EVALUATE NEXT OPPORTUNITY** Priority: Accident: Project: Incident:

**Non Service Request Tasks** 

Task: AC FILTER-30 - Replace Return Air And Fresh Filters -30 Day Warranty: NO WAC: Reason: Work Class: Comments: Task: BTC180-PM - Btc 180 Day Class Pm Warranty: NO WAC: Reason: Work Class: Comments:

Overhead

Small Parts - Labor: 0.00 Tools: 0.00 Total Overhead Costs: 0.00

Small Parts - Parts: 0.00 Overhead Costs: 0.00



Page 1 of 5

©2020 AssetWorks Inc. All Rights Reserved. Report Date: 5/11/2020

PM Checklist				
Task / Comment AC FILTER-30	Exception PM: No	e Failed	N/A	Completed
PM5840 - REPLACE RETURN		AM		
PHISONO - REPLACE RETURN	AIN AND FRESULTETING	A		V
BTC180-PM	Exception PM: No	_		_/
PM448 BLIND TRAINSPECTION	AILER COACH 180-DAY			V
PM110 SHEET ME	TAL WORKER	T.L AP		(a)
PM323 - CHECK UNDERCAR LOOSENING AND DAMAGE	PIPING FOR SIGNS OF	T.L WP		
PM330 - INSPECT ALL PIPIN THAT SHOW SIGNS	IG, VALVES, HOSES & FITTINGS			W
Procedure: OF LEAKSÝ ABRA HAVE MISSING OR BROKEN BELIEVED TO HAVE RESTRI	COMPONENTS OR ARE	T. C # 1		
PM338 - FLUSH AND CLEAN EVAPORATOR COILS	DRAINPAN UNDER	T-C HP		V
PM339 - REPAIR ANY TORN	OR MISSING PIPE INSULATION	TC MP		
PM720 - RECONNECT HOSE	S FROM CAR BODY TO TRUCKS	TCHP		
PM721 - AVAILABLE FOR LE AIR TEST	AK REPAIR DURING SINGLE CAR	T.C. WP		V
PM117 CARMAN -	*********	\$ □		Z,
PM324 - INSPECT ALL BRAK BRAKES FOR PROPER	E EQUIP INCL. VALVES TREAD	of $\square$		
Procedure: OPERATIONÝ SE BUSHINGS AND COTTER KE	CUREMENT OF ALL BOLTS AND YS			_/
PM325 - INSPECT TRUCK FF COMPONENTS FOR PROPER	RAME AND TRUCK-MOUNTED	03		
	ER BUSHINGSÝ AIR SPRING RSÝ JOURNAL BOX AND			
PM817 - CHECK ALL EQUALI DAMAGE, REPLACE AS REQ	IZER BEAM BUSHINGS FOR	>14 [		
Procedure: UIRED - 8 LOCA FRA 238.303(C)(5)(IV)	TIONS PER COACH RMM 12.2.3			
PM326 - INSPECT WHEELS / REPORT	AXLES AND COMPLETE WHEEL	GO [		$\Box$
PM327 - CHANGE BRAKE SH	OES AS NEEDED	an $\square$		4
PM328 - INSPECT COUPLER HEIGHT AND CONDITION	S AND COUPLER PARTS FOR	\$\bullet \sum_		1
Procedure: RECORD ON CRN FRA-238.303(E)(3)	4-3A RMM-3.2 FRA			

Report Date: 5/11/2020

Work Order Detail

PM329 - INSPECT DRAFT GEAR - TIGHTNESS IN POCKET, NK. CRACKING, Procedure: OTHER DAMAGES PM637 - INSPECT WELDED BRACKETS USED TO ATTACH HANDRAILS ON BOMBARDI Procedure: ER COACHES (300'SY 600'S AND 1600'S) AND ON KAWASAKI COACHES (700-766Y AND 1700 S). ALSO INSPECT WELDED BRACKETS AT UNCOUPLING LEVERS ON ALL KAWASAKI COACHES (700 SY 900 SY AND 1700 S). PM331 - INSPECT ENTIRE CAR BODY FOR LOOSE, DEFECTIVE AND Procedure: MISSING PARTSÝ TO INCLUDE LUGGAGE RACKSÝ SEATSÝ SEAT ATTACHMENTS AND TRAPS RMM-1.4.1.A FRA FRA-238.307(C)(1) PM332 - CLEAN FRESH AIR INTAKE SCREEN AT BOTH ENDS PM333 - TEST AND LUBRICATE THE HANDBRAKE PM334 - INSPECT FIRE EXTINGUISHER FOR PROPER GAUGE ROOHY AND DATE AND VERI Procedure: FY PIN AND SEAL ARE INTACT FRA-238.307(C) (4) PM335 - INSPECT FOR EMERGENCY PRY BAR IN PLACE PM336 - LUBRICATE ALL MOVEABLE PARTS INCLUDING DOOR TRACKS AND Procedure: ROLLERS WITH DRY GRAPHITE PM337 - REPLACE BAD-ODOR SPONGE AT BOTH ENDS OF CAR ROOHX PM651 - INSPECT ALL SEATS, SEAT CUSHIONS AND SEAT ATTACHMENTS FOR BR Procedure: OKENÝ LOOSEÝ OR SHARP EDGES RMM-1.4.1.A FRA FRA-238.307(C)(1) PM340 - VERIFY PROPER OPERATION OF EMERGENCY EXIT WINDOW Procedure: LOCATION AND RECORD Ý PM341 - CHECK FOR PROPER EMERGENCY SIGNAGE INTERIOR AND EXTERIOR AND Procedure: HIGH VOLTAGE SIGNS. PM341.2 - INSPECT LOW LEVEL EXIT PATH MARKING (LLEPM) SIGNAGE PM342 - FUNCTIONALLY TEST OPERATION OF POWER DOOR RELEASE MECHANISMS Procedure: BOTH INTERIOR AND EXTERIOR - POWER DOOR EQUIPPED COACHES ONLY. PM575 - TEST ALL EMERGENCY VALVES (CONDUCTORS VALVES)



Page 3 of 5

Report Date: 5/11/2020

Work Order: MRDVSH-2020-487

Work Order Detail

PM343 - PERFORM SINGLE CAR AIR TEST (RECORD ON CRM-3A)	09		1
Procedure: NOT ON 180 DAY IN LINE INSPECTION EXCEPT IF CONDITIONS WARRANT			
PM574 - REPLACE E-TYPE FILTER CARTRIDGE			u
PM610 - CHECK FOR FIRST AID KIT AND REPLENISH AS NECESSARY	ROOHS [		
PM360 - CLEAN RETURN AIR FILTER GRILLS	En L	Ш	4
PM454 ELECTRICAL			
PM345 - INSPECT ALL UNDERSIDE CONDUIT AND ENCLOSURES FOR SIGNS OF	BH Em		9
Procedure: DAMAGE AND SEAL INTEGRITY  PM346 - CHECK UNDER CAR HIGH AND LOW VOLTAGE  WIRING AND CABLING AND	DH		9
Procedure: ELECTRICAL EQUIPMENT FOR SIGNS OF DAMAGE OR OVERHEATING			
PM347 - CHECK ALL WHEEL SENSORS AND CABLING FOR SIGNS OF DAMAGE AND	BHEM		4
Procedure: PROPER GAP		100	
PM348 - INSPECT AND CLEAN ALL JUMPERS AND JUMPER RECEPTACLES	BH EM		
PM349 - REPAIR OR REPLACE AS NEEDED ALL GROUND STRAPS AND CABLES	BHEM		4
PM712 - REPAIR AND REPLACE TRAP HEATERS (AS NEEDED)	DH -		4
PM350 - TEST ALL M.U. AND SIGNAL CIRCUITS	DHEM		4
PM351 - CHECK ALL SWITCHES, RELAYS, CONTACTORS, SHUNT TRIPS, WIRING	DH EM		
Procedure: CONNECTIONS AND CIRCUIT BREAKERS FOR PROPER OPERATIONSY SIGNS OF LOOSENING AND OVERHEATING.			
PM352 - REPLACE AS NEEDED HEAD LIGHTS, BRAKE INDICATOR LIGHTS, CLASS	BHEM [		4
Procedure: LIGHTSÝ NUMBER LIGHTSÝ STEP LIGHTSÝ EMERGENCY LIGHTS AND GENERAL LIGHTING.		_	
PM353 - TEST WHEEL SLIDE SYSTEM FOR PROPER OPERATION AND SECURE CONT	BH EM		
Procedure: ROL BOX			
PM354 - CLEAN AND VACUUM ALL ELECTRICAL LOCKERS	13 A _		
PM355 - CHECK FOR PROPER OPERATION OF H.V.A.C. CONTROLS AND THERMOST	BB, AM		
Procedure: ATS			
PM356 - CHECK THE EVAPORATOR BLOWER AND CONDENSER FANS FOR PROPER	BB, AM		Ly
Procedure: WORKING CONDITION			



Work Order: MRDVSH-2020-487

### Work Order Detail

Work Order: MRDVSH-2020-487

PM357 - REPLACE RETURN AIR AND FRESH AIR INTAKE FILTERS	AM	V
PM358 - INSPECT ENTIRE H.V.A.C. SYSTEM FOR LOOSE OR MISSING COMPONEN	BB, AM	
Procedure: TS, LEAKS AND SIGNS OF EXCESSIVE VIBRATION		
PM359 - INSPECT COMPRESSOR FOR PROPER OIL LEVEL AND RECEIVER TANK FO	BB, AM	
Procedure: R PROPER REFRIGERANT LEVEL		
PM362 - TEST HIGH AND LOW VOLTAGE SYSTEMS FOR GROUNDS	OH	y
PM363 - INSPECT AND REPAIR TRAP HEATERS AS NEEDED	ort 🗆 🗖	, P
PM638 - TEST POWER DOOR OPERATION-POWER DOOR EQUIPPED COACHES ONLY	gd 🗆 🗡	
PM361 - CLEAN SURFACE OF CONDENSER COILS	BOIM [	

#### Comments:

180 DAY

Internal Parts Cost:	
Internal Labor Cost:	
Commercial Parts Cost:	\$0.00
Commercial Labor Cost:	\$0.00
Commercial Misc Cost:	\$0.00
Commercial Tax & Markup:	\$0.00
Equipment Usage Costs:	\$0.00
Overhead Costs:	\$0.00
Internal Total:	\$0.00
Commercial Total:	0.00
Work Order Total:	\$0.00



Page 5 of 5

Report Date: 5/11/2020



# COACH COUPLER INSPECTION REPORT



Coach #:

For any maintenance and/or replacement

Task	Description	Other reference	Front	Rear
	Inspect Coupler to Include:			
1.	Visually Inspect Coupler for Proper Coupling, damage and Body Integrity	FRA-238.303(e)(3) APTA PR-M-RP-002-98	GM	GM
2.	Gauge Coupler for 31000 34100-1 34100-2A (if required) 32600 34101-4 44250-5	APTA PR-M-RP-002-98	GM	Gn
3.	Inspect Coupler lock + lock drop/ and inspect for proper coupling CHECK "TELLTALE" IS CLEAR, NO OBSTRUCTION.	APTA PR-M-RP-002-98	GM	GM
4.	Inspect Coupler Anti-Creep+ Draft Gear for Excessive Wear, Loose or Cracked Welds in Pocket	FRA-238.303(e)(3) APTA PR-M-RP-002-98	GM	an
5.	Coupler Lock Lift (Special Lock) lever and Operating Rod Eye Clearance.	APTA PR-M-RP-002-98	GM	GM
6.	Inspect Coupler Free Slack	APTA PR-M-RP-002-98	om	an
7.	Inspect Coupler Left Level Coupler as Required, Measure Height+ Record on Document# HRU-3	HRU-3	Gn	GM
8.	Perform Coupler Carrier Inspection	FRA-238.303(e)(3) APTA PR-M-RP-002-98	GM	an
	Record all Defects on Form MR1			

	Record all Defects on Form MR1	
Date:	5-11-20	Employee: MC Mflaw
Employee	ID:	Employee Signature:
Foreman:	Family 1	Foreman Signature:
CS-ME-FO-2	10072 Rev. 4	11/6/2018 Coupler Inspection Report

Keolis

Coach #: 233

#### COACH WHEEL REPORT



5-11-20 WHEEL MEASURE Test Date: FLANGE FLANGE FLANGE HEIGHT FLANGE HEIGHT THICKNESS POS. THICKNESS THICKNESS **THICKNESS** POS. [LIMIT: 1 7/16"] [LIMIT: 1 1/18"] [LIMIT: 1 1/18"] [LIMIT: 1"] [LIMIT: 17/16"] [LIMIT: 1"] L1 R1 L2 R2 13 R3 L4 R4 Comments: TOP OF RAIL CLEARANCE HEIGHT COUPLER HEIGHT PILOT HEIGHT FLOOR HEIGHT (MAX. 34 1/2" MIN. 32 1/2") (MAX. 6" MIN. 4") (51 in±1.0") 1R 5/20 FRONT FRONT 2R 570 REAR AIR SPRING VERIFICATION INSPECTION AIR SPRING HEIGHT AIR NO. 1 END 56 LBS. SPRING R2 PRESSURE SINGLE CAR TEST PRESSURES FULL ASP BCP **EMERGENCY** SERVICE DEFLATED DEFLATED **AWO** AW0 AW3 AW3 Employee: 1530 Foreman:

Officer:

Keolis

#### MBTA COMMUTER RAIL COACH WHEEL SLIDE REPORT

VEHICLE NO:	233 DATE	5/4/20	LOCATION:	Reado, UE
	DE CONTROL UNIT:			
	Wheel Slide Control Un performance test	tit System	COMMENTS:	
	Electronic panels, cards lights and fuses	s, wires, test		
	Speed sensor resistance	check		
	#2 950 #3 950 #4 965	Signature:	_ SH	
PNEUMATIO	CS:		COMMENTS:	
	A & B valve operation			
	В	Signature:	BH	
		Diganture.		
SPEED SENS	SORS AND CABLES:		COMMENTS:	
	Speed sensor cables		-	
	Proper sensor			
	Speed sensor gap			
	gear	Signature:	BH	
DEFERRED		SEVERITY A - HOLD CAR B - SCHEDULE I C - MONITOR		RECOMMENDED SEVERITY CODE
5557500		700 000		
SYSTEM STA	ATUS:			, ——
	FUNCTIONING	Foreman	Ar	)
	NOT FUNCTIONING	Signature:	1/10	

# MBTA COMMUTER RAIL HVAC SYSTEM INSPECTION for Single Level Coaches

Bombardier Coaches 600-653, 1600-1652 (Faiveley A/C System R-22) Bombardier Coaches 350-389, (Stone Safety A/C System R-22) MBB Coaches 500-532, 1500-1533 (Sigma A/C System R-22) Pullman Coaches 200-257 (Stone Safety A/C System R-22)

С	ELECTRIC LABOR CARN OACH CLEAN	ER MEN	SIGNATURE D. JAHUT AJMANAON	EMP. ID #		NUMBER: 2	<u>233</u> 5-11-2020
RE	QUIRED TOO				clamp-on Ammeter and		
			tachments, Megon ristle Brush, Rubbe		c Leak Detector, HVAC N dder	vianiioid Gac	iges,
	And the And the And	BE STI	RICTLY ADHERED	TO. FOLLOW ETERMINING IF	PMENT TAG OUT PRO SPECIFIC PROCEDUR EQUIPMENT IS TO BE	E	
	-					PASS	FAIL
1.			el in lower sight gla o leak detection/re		ank is visible.		
2.	B - [18] [18] [18] [18] [18] [18] [18] [18]		and electronic leak ns, fittings, valves,		eon leaks and traces of indenser coils, etc.		
3.	Vacuum air in flow.	itake co	ompartment and ch	neck evaporator	pan and drains for water	W	
4.	Wash return a	air grill.				/	
5.	Check all mot	tors an	d mounts for secur	ement and deter	rioration/damage.	V	
6.	Inspect air flo	w boot	s for integrity and p	proper attachmer	nt.	W	
7.	Inspect all co		s, that control com	pressor, conden	ser fan, heaters, and	•	
8.	Blow all contr	ol boxe	es with air to clean	any debris from	them.		
9.	Clean dirt and Check for pro			ensors and temp	perature control units.		
10.	Replace air fi	lters ar	nd Bad Odor Spon	ges.			
						PASS	FAIL

	Megger test compresso Megohmeter.	r, condenser fan, and blow	er motors for grounds with	
	+ ,	of all avantaged (30, 80, O'e)	and floor heaters (30-50)	O's)
		of all overhead (30-80 Ω's)		223).
		r circuit to ground (>2M $\Omega$ ). May through November (		
217	1.0			Maintow Co
3.		of all protective heaters (10	10 30 323).	/ VIN.
	Megger test from heate	r circuit to ground (>2M $\Omega$ ).		
14.	Inspect and test operat	ion of air flow switch and ov	verhead heat thermostat	
	(Klixon).			
15.	Inspect all motors and	record current draw on all p	hases.	
	EVAPORATOR BLO	MED		
		CONDENSER F	AN MOTOR #1 COL	MPRESSOR MOTOR
	MOTOR #1			nase A ZZ-H
	Phase A 1.3	_ Phase A	C-1 E	
	Phase B 1,4	_ Phase B _	APPLICATION OF THE PROPERTY OF	hase B 22.1
	Phase C 1,4	Phase C	2.60 Pr	nase C 22.0
	EVAPORATOR BLO	WER		
	MOTOR #2	CONDENSER F	AN MOTOR #2	
	Phase A 14	Phase A	2.1	
	Phase B 1.3	Phase B	211	
	Phase C 1/3	Phase C	2.2	
16.	Check for proper rotation	on and air flow of condense	er fan and blower motors.	
17.	Check thermal expans	ion valve bulbs for proper s	ecurement.	
	PUT HVAC SYSTEM	ON AUTOMATIC AND CH	HECK FOR PROPER OPE	ERATION
ATES			1. 1. 1	
18.		gh May 1st apply manifold		
		ostic equipment (TEST BO)	A). Operate the system at	
	record Freon pressure	1 END	No. 1	2 END
	Line valve THX	Modulation THX	Line valve THX	Modulation THX
	Low Side	Low Side	Low Side	Low Side
	Suction Pressure	Suction Pressure	Suction Pressure	Suction Pressure
	Saturation Temp.	Saturation Temp.	Saturation Temp.	Saturation Temp.
	(from chart)	(from chart)	(from chart)	(from chart)
	N. Action of the state of the		\ \	1/
	Suction Temp	Suction Temp	Suction Temp	Suction Temp
	SUPERHEAT	SUPERHEAT	SUPERHEAT	SUPERHEAT
		High	Side	-
	Ambient Torresent		Discharge Pressure	
	Ambient Temperature		Discharge Fressure_	

PASS FAIL

19.	Charge system as necessary to maintain Freon level 1/2 full on lower sight glass. (Nominal: 270 - 275 psig)
20.	Cover condenser coils with cardboard to cause #2 condenser fan to operate.  (Nominal: 250 psig)  START PRESSURE:
21.	Restrict compressor suction valve to lower system pressure, until shutdown.  (Nominal: 20 to 25 psig)  SHUTDOWN PRESSURE: 12  REOPEN SUCTION VALVE
22.	Block condenser completely to cause system to go into modulation, if necessary heat coach prior to attempting modulation to cause a higher pressure. (Nominal: 380 - 400 psig)  MODULATION PRESSURE: 390  Observe that modulation occurs and continues to operate in modulation until a pressure of 330 +/-10 psig is reached. (When modulation occurs you will see a sudden drop in pressure around 400 psig).
23.	Block condenser completely to cause system to shutdown on high pressure, if necessary heat coach prior to attempting shutdown to cause a higher pressure.  (Nominal: 425 - 430 psig)  SHUTDOWN PRESSURE:
24.	Record the loading pressure and the unloading pressure for each head.  (place a heat load on the coach and use suction valve)  1st stage unloader LOADED: 64
25.	Check system for moisture at the filter dryer sight glass indicator, if indicator is pink in color, or the sight glass indicates moisture, checked failed. If failed change the filter/dryer.
	Between Nov 1st through May 1st take oil sample (Acid Test) use test kit.  Follow the oil sample kit instructions to determine condition of the compressor oil and record result.  MARGINAL PASS FAIL N/A
41,	Wash condenser compressor unit and associated piping.

PASS FAIL

28	Using the DTE (Diagnostic Test Equipment) raise the temperature in the coach so that Full Cool will be called for. (>75°F)		
29	Remove the DTE and observe that the coach responds properly moving from Full Cool to Partial Cool. Verify that the modulation valves deenergize. (Appox. $74^{\circ}F$ )		
30	When the Coach gets cooler Reheat is energized. Verify 1st stage OH heat contactors close. (Approx. 72°F)		
31	The Coach should continue to cool until Partial cool drops out. Verify Compressor contactor is Open. (Approx. 71°F)	V	

Reviewed by

FOREMAN

MANAGER

#### APPENDIX A

#### Resistance Chart

	100 X X X X X X X X X X X X X X X X X X	11.0	
200	OH - 1st Stage	75+- 2.5	Ω
	OH - 2nd Stage	47.5+- 2.5	Ω
	FH - 1st Stage	32.5 +- 2.5	Ω
	FH - 2nd Stage	Disabled	
300	OH - 1st Stage	75+- 2.5	Ω
	OH - 2nd Stage	47.5+- 2.5	Ω
	FH - 1st & 2nd Stage	52.5 +-2.5	Ω
500	OH - 1st Stage	67.5 +- 2.5	Ω
	OH - 2nd Stage	35 +- 5	Ω
	FH - 1st & 2nd Stage	35 +- 5	Ω
600	OH - 1st Stage	57.5 +- 2.5	Ω
	OH - 2nd Stage	37.5 +- 2.5	Ω
	FH - 1st & 2nd Stage	32.5 +- 2.5	Ω



#### REFRIGERANT USAGE AND LEAK REPAIR RECORD

The EPA, in accordance with Section 608 of the CLEAN AIR ACT, requires record keeping of refrigerant usage and leak repairs for comfort cooling systems with a charge of 50 pounds or greater. All single level coaches have approximately a 55 pound charge. Kawasaki coaches have a 33 pound charge in each end. Any leak with an annual leak rate greater than 15% of system capacity must be repaired.

Coach	233 Date	5-11-	2020	Location	READUILLE
Defect					
Repair					
Amount	t of Refrigerant recovered from sys	stem	-0		
	of recovered Refrigerant reinstall		-0		
	t of new Refrigerant charged to sy		-0	_	
	t of Refrigerant drawn from stores		-0	_	

				Sing	le-leve	el				_		Bi	-level		
					SYSTE						VS	RS 3	3# SYS	STEM	
#	%	#	%	#	%	#	%	#	%	#	9/0	#	%	#	%
1	1.8	12	21.8	23	41.8	34	61.8	45	81.8	1	3.0	12	36.4	23	69.7
2	3.6	13	-	24	43.6	35	63.6	46	83.6	2	6.1	13	39.4	24	72.7
3	5.5	14	25,5	25	45.5	36	65.5	47	85.5	3	9.1	14	42.4	25	75.8
4	7.3	15		26	47.3	37	67.3	48	87.3	4	12.1	15	45.5	26	78.8
5	9.1	16	-	27	49.1	38	69.1	49	89.1	5	15.2	16	48.5	27	81.8
6	10.9	17	30.9	28	50.9	39	70.9	50	90.9	6	18.2	17	51.5	28	84.8
7	12.7	18	32.7	29	52.7	40	72.7	51	92.7	7	21.2	18	54.5	29	87.9
8	14.5	19	34.5	30	54.5	41	74.5	52	94.5	8	24.2	19	57.6	30	90.9
9	16.4	20	36.4	31	56.4	42	76.4	53	96.4	9	27.3	20	60.6	31	93.9
10	18.2	21	38.2	32	58.2	43	78.2	54	98.2	10	30.3	21	63.6	32	97.0
11	-	22	40.0	33	60.0	44	80.0	55	100.0	11	33.3	22	66.7	33	100.0

Alstom	Bi-level					
Alte 13# Circuits						
#	%					
1	8					
2	15					
3	23					
4	31					
5	38					
6	46					
7	54					
8	62					
9	69					
10	77					
11	85					
12	92					
13	100					

Has the system been charged in the past 12 months?

If yes, what was the percentage of system capacity charged?

What is the percentage of system capacity charged for this repair?

Total percentage charged past 12 months

Technician

Foreman

Copies of this form are to go into the coach file and into the Preon control file.



# MAINTENANCE & REPAIR FORM

	<u> </u>	DATE _				TRAIN #				
	COACH	92 DAY		1 YR		2 YR				
د د۶	LOCO	The Late Control of the Control of t		1 YR		3 YR		5 YR		
Loco/Cab Car	coach 233	Coach	Coach	Coach	Coach	Coach	Coach	Coach	Loco/Cab Car	
LOC	D/COACH # &	DEFECT I	FOUND	COR	RECTIVE ACT	ON TAKEN	& DATE	SIGNATUR	E #	
1	12000	IT C	over	0.	EPLACES	) /2/	100	0.4		
B	RoKen			KE	ETLACES	COL	er	Btt		
	onduct.				D/ A	ad				
Во	zzeR	NOT	WORKING	5 15	BUZ	zer	8	DU	+	
4-1	nissioner	16 L	180voit		Replac	ED		BH		
re		7010	,,,,,		111 5					
	5/11/2	20					M	/		
-	DATE				-	F	OREMAN IN CH	ARGE		



# **EMERGENCY LIGHTING DURATION TEST RECORD**

# **All Single-Level Coaches**

			ave been charged for 30				
At the	All eme				Record a	ny failures a nents on MR	2.107
ND S		-	LIGHTING ARRANGEN	MENT	12		#1 END 200 - 258 SERIES BT
ND (			LIGHTING ARRANGEN	IENT IS			# 1 END 350 - 389 SERJES B
ND			LIGHTING ARRANGEN	16 RENT			# 1 END 600 - 1606 SERIES BTC
ND		1. 1	LIGHTING ARRANGE	MENT			#1 END 500 - 1500 SERIES BT(

NOTE: Refer to instructions for performing tests on Page 2 if needed.



# EMERGENCY LIGHTING DURATION TEST RECORD All Single-Level Coaches

#### INSTRUCTIONS:

Before beginning, verify the following: Any/All emergency lighting ballast replacements have been completed.

- 1. The emergency lighting ballasts have been charging for at least 30 minutes.
- Ensure the main lighting circuit breaker is ON, all individual light switches are ON, and when equipped, the emergency light cutout switch in the circuit breaker control panel is in the NORMAL position.
- 3. Verify all regular inside coach lighting in ON.
- 4. Turn the main lighting circuit breaker OFF.
- 5. Verify all emergency lighting comes ON.
- Verify emergency lighting remains ON for 60 minutes. If at any point in the 60-minute period the emergency lighting stops functioning altogether, record its duration on the MR1 form, then refer to the NOTE that follows Step 10.
- At the end of 60 minutes, record the results in the spaces provided on the record sheet.
- 8. Turn the main lighting circuit breaker ON after testing /recording is complete.
- Ensure the record sheet is fully completed, then submit it to the Foreman on duty. The completed record sheet is to be included in the PM completed work order and control forms package.
- Charge the emergency ballasts for 30 minutes.

NOTE: If any of the steps fail to perform as expected, consult the OEM manual as needed, and troubleshoot/repair/replace parts. If all the emergency lighting fails early, begin by double-checking that the ballast actually did charge a full 30 minutes prior to testing. Retest. Provide PM comments or open a Service Order, whichever is applicable.