564109, B.C. Ltd. DBA J&L Consulting
Appraisal Intake Sheet
November, 2024

Confirm that reporting marks & number / locomotive models are correct as listed

Questions/Information Required	JLCX 100 - RP20BD	JLCX 101 - RP20BD	JLCX 2049 - GP20	JLCX 2033 - SD20E	JLCX 2105 - GP38	JLCX 5232 - GP38
*Unit reporting marks and number						
*Make/model	RP20BD	RP20BD	GP20E	SD20E	GP38-3	GP38-2
Is unit in operating condition	Yes	No	Yes	Yes	In shop for overhaul	Yes completing overhaul
Type of block	Deutz 3 engine	Deutz 3 engine	16-645D3A	16-645E	16-645E	16-645E
Wheel bearing type (oil, rotating endcap)	Hyatt	Hyatt	Hyatt	Hyatt	Hyatt	Hyatt
Type of air brake valves	26L	26L	26L	26L	26L	26L
Any block heaters	Yes	Yes	Yes	Yes	APU	APU
Last wheel report	3"	2"	2" plus	2" plus	New installing	2.5" plus
Type of couplers (ex alignment control)						
Condition of electrical system	Good	removed	Good	Great	All new TMV instlaling	Great
Is unit Blue Carded	YES	no	Yes	Yes	after overhaul	After overhaul
Condition of body & frame	Great	Good	Good	Good	Great	Great
AAR control stand Y or N	Yes	Yes	Yes	Yes	Yes	Yes Moved to SHF