Work Order Detail for Asset 256

Work Order: **MRDVYD-2021-429 APC EQUIPMENT REMOVED - COACH BEING REMOVED FROM FLEET**
Status: **CLOSED**

Dept: **MECH - MECHANICAL** Warranty: **NO**

Asset No: **256 - 1978 PULLMAN/MK BTC-1C COACH - POWER DOOR** Serial No: **256**
License:

Asset No:		Opened By:	**ANDREA.FORD**	Date In:	**01/28/2021 11:01**
Eq Type:	**1978-PULLMAN/MK-BTC-1C**	Current Equip Status:		Date Due:	**03/14/2021 11:01**
Job Type:	**REPAIR**	Account:	**254-530001**	Opened:	**01/28/2021 11:01**
Meter 1:	**0.00**	Reference WO:		Finished:	**01/28/2021 11:01**
Meter 2:	**0.00**	Estimated Hours:	**0.00**	Closed:	**01/28/2021 11:01**
Shop Hrs:	**0.00**	User Hours:	**0.00**	Warranty Expire:	

Priority: **M4 - EVALUATE NEXT OPPORTUNITY** Accident:
Incident: Project:

Non Service Request Tasks

Task: **C17-250 - Equipment Transport Prep** Warranty: **NO**

WAC: Reason: **C - WEAR AND TEAR**
Work Class: Comments:

Overhead

Small Parts - Labor: **0.00** Tools: **0.00** Total Overhead Costs: **0.00**
Small Parts - Parts: **0.00** Overhead Costs: **0.00**

Comments:

COACH WILL BE SHIPPED TO SEAVIEW TO BE REMOVED FROM FLEET. APC TEAM REMOVED THE FOLLOWING APC EQUIPMENT ON 1/23/21:

2 NEMAS
2 FBDS
1 BRIDGE

EQUIPMENT REMOVED WILL BE REUSED ONCE CLEARED FROM MTHINX.

Internal Parts Cost:	
Internal Labor Cost:	
Commercial Parts Cost:	$0.00
Commercial Labor Cost:	$0.00
Commercial Misc Cost:	$0.00
Commercial Tax & Markup:	$0.00
Equipment Usage Costs:	$0.00
Overhead Costs:	$0.00
Internal Total:	**$0.00**
Commercial Total:	**0.00**
Work Order Total:	**$0.00**

Trapeze™ **©2021 AssetWorks Inc. All Rights Reserved.**