

MAINTENANCE LOG

CAR# 2005

DATE

TECH/S

WORK PERFORMED (use multiple lines)[illegible]

MAINTENANCE LOG

CAR# 2005

DATE	TECH/S	WORK PERFORMED (use multiple lines)
8/22/18	SW, RK, CB	F-End Engine - REINSTALL #1 ROCKER HOUSING AND Oil Pan. Hook up Coolant & oil lines
8/23/18	RK, CB	F-End Engine - Check Injector Timing SET INJECTOR TRAVEL & VALVE LASH Repair oil pick up line where it bolts to oil pan Drill out 2 hole & Heli-Coil
8/29/18	CAT	RE-ATTACHED F-END CB BRAKE ^{APPL} VALVE BRACKET TO UNDER BELLY
9/4/18	SW	F-End Engine Finish Hooking up Coolant Lines & Tighten Add Antifreeze Leaking at Right Side of Aftercooler Drain Anti-Freeze
9/5/18	SW	F-End Engine - Replace Rubber Hose Connection on Right Side Aftercooler line Refill with Anti-Freeze REPLACE Fuel line - Filter Filter to Pump AND MAIN RETURN Fuel line
9/7/18	SW	Pull OUTSIDE AND START UP F-END STARTED & NUMBER #1 HEAD GASLET Leaking Compression Need to ReDo PUSH BACK #1 & Drain Anti-Freeze
9/10-9/21	SW, RK	Pull F-End Engine BACK APART Shim #1 Liner Put Engine Back together Fix Water Leaks on LUBE oil Colder AND Inter Cooler (Rubber Hoses) START UP ON 9/21 to TEST

MAINTENANCE LOG

CAR# 2005

DATE	TECH/S	WORK PERFORMED (use multiple lines)
4/24/18	SW/CT	REPLACE 7HV TO 2HV CONVERTER STARTS DPU
4/25/18	CT	FILL BATTERIES WITH WATER
5/31/18	SW	F-END REPLACE STARTER PROP. ENGINE
		FUEL LINE TO STARTER
		AIR LINE TO STARTER
6/7/18	SW	LOOK AT TEMP SWITCH ON RADIATOR F-END
		SWITCH IS BAD CONTACTS STUCK CLOSED
6/12/18	SW, RK, CB	AIR WORK CLEAN CHECK VALVES, PZA ON B-END
6/21/18	SW	LOOK AT AIRBRAKES CHANGE C-1 RELAY VALUE
8/14/18	SW, RK	TEST AIR GAUGES F&B END
	CT	REPLACE AC CONTACTOR (480V)
	CT	REPLACE TEMP SWITCH FOR COOLING FANS F-END
		CHANGE WIRING SO BOTH COOLING FANS ARE ¹⁶⁵ ₁₈₀
		CONTROLLED BY TEMP SWITCH
	SW, RK F-END	REMOVE VALVE COVERS TO CHECK VALVE SETTINGS
		FIND #1 VALVE BRIDGE BROKEN along with
		EXHAUST VALVE DRAIN ANTI-FREEZE
8/15 & 8/16	SW, RK	F-END ENGINE REMOVE ROCKER HOUSING &
		HEAD. FOUND #1 PISTON BADLY
		DAMAGED
		REMOVE OIL PAN AND TAKE PISTON
		& ROD OUT ORDER PARTS
8/17/18	RK.	F-END ENGINE REPLACE #2 ROCKER HOUSING
		DUE TO OIL LEAKING AT ENDS OF SHAFT
8/21/18	SW, RK, CB	F-END ENGINE - INSTALL NEW LINER & HEAD &
		PISTON