

Hi Brian,

Sorry for the delay in getting this information to you.

I've attached a Data Sheet for your locomotive. Your unit information is the NW2, built after 1945 (the last column).

I spoke with Steve. He said the compressor on your unit will need rebuilt, probably just the top end. You have a 567 "A" Engine, with the Power Assembly components: "B" Head, "E" Liner, "E" Piston & "E" Rod.

I hope this information is helpful. If you have any questions or need anything further, please feel free to contact any one of us.