

Wheel Inspection Report - 4 Axel / 6 Axel

Date: 6/4/20 1501

Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		32	1 1/4	1 3/16	1/8
2		32	1 3/8	1 1/16	1/8
3		21	1 1/8	1 5/16	1/8
4		40	1 1/4	1 3/16	1/8
5					
6					

Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		32	1 3/8	1 7/16	1/8
2		31	1 1/2	1 1/8	1/8
3		22	1 3/16	1 5/16	1/8
4		41	1 1/4	1 3/16	1/8
5					
6					