

Wheel Inspection Report - 4 Axel / 6 Axel

Date: 4/21/20 1503

Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		44	1 7/16	1 1/4	1/8
2		45	1 3/8	1 3/16	1/8
3		22	1 3/16	1 1/4	1/8
4		37	1 3/16	1 1/4	1/8
5					
6					

Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		45	1 7/16	1 3/16	1/8
2		46	1 7/16	1 5/16	1/8
3		24	1 7/16	1 1/4	1/8
4		38	1 3/8	1 5/16	1/8
5					
6					