

Wheel Inspection Report - 4 Axel / 6 Axel

Date: 3/10/20 4001

Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		1 1/8	1 1/2	1 1/4	1/8
2		1 1/2	1 1/16	1 1/4	1/8
3		1 1/2	1 1/4	1 1/4	1/8
4		1 1/4	1 1/2	1 1/8	1/8
5		1 1/8	1 1/2	1 1/4	1/8
6		1 11/16	1 1/4	1 1/4	1/8

Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		1 7/16	1 1/8	1 1/4	1/8
2		1 5/8	1 1/2	1 1/4	1/8
3		1 1/2	1 11/16	1 1/4	1/8
4		1 5/8	1	1 11/16	1/8
5		1 9/16	1 1/2	1 1/4	1/8
6		1 11/16	1 1/8	1 1/16	1/8