

WHEEL REPORT





Car No: SDCX 56

Gage Type: Precision Gage and Tool, S-618

Inspection Date: 3-11-2021

Calibration Date: 2-1-2021, PABCO

Inspector:

	Gage	Frac.		Frac.	Gage		
			1			2	
							
Rim T	43	2-5/8"		2-3/4"	44	Rim T	
Flange H	0-1	1-1/8"		1-1/8"	0-1	Flange H	
Flange T	0-0 +	1-1/4"		1-1/4"	0-0 +	Flange T	
			3			4	
							
Rim T	44	2-3/4"		2-3/4"	44	Rim T	
Flange H	0-1	1-1/8"		1-1/8"	0-1	Flange H	
Flange T	0-0 +	1-1/4"		1-1/4"	0-0 +	Flange T	
			5			6	
							
Rim T	43	2-5/8"		2-5/8"	43	Rim T	
Flange H	0-2	1-3/16"		1-3/16"	0-2	Flange H	
Flange T	0-0 +	1-1/4"		1-1/4"	0-0 +	Flange T	
			7			8	
							
Rim T	43	2-5/8"		2-3/4"	44	Rim T	
Flange H	0-2	1-3/16"		1-3/16"	0-2	Flange H	
Flange T	0-0 +	1-1/4"		1-1/4"	0-0 +	Flange T	

Note: Flange height rounded up to the largest 1/16" per gage standards