

SILVER FOOT 800279 June 2021

MAP #9

Maintenance Analysis Program Worksheet

Defect(s) found during Inspection		Corrective Action Taken (Define action(s) taken to resolve defect)	WMS WO# (If Applicable)	Signature (Employee Completing Corrective Action)
Replace disc pad #5 outboard		Replaced		JEFF GILANYI
Replace disc pad #7 outboard		Replaced		1
B-end out of date Brake Pipe tail hose replace		Replaced		
B-end out of date MR tail hose		Replaced		
#8 brake cylinder boot loose		Repaired		
Replace # 6 outboard and inboard brake pads		Replaced		
Unsecured crossover hose bracked B-end		Secured		
Unsecured decelostate hose, secure		Secured		
Unsecured car to truck decelostat hose		Secured		7
Replace B-end brake pipe tail hose		Replaced		
#4 equalizer rubbing		Repaired		1
		pleted at time of closing this form; a W		be opened for any
Employee Validating Inspection (Print Legibly) Date / Time of Inspection The above inspection has been performed, with exceptions as noted, and the report is approved.		Employee Validating Corrective Action Completed (Print Legibly) G-9-2/ Date / Time corrective work validated The above corrective actions have been performed, except as noted, and the report is approved.		
Signature	Occupation	Signature		Occupation
Date / Time Unit Released for Service: 6-9-21 Train or Unit Number:	Print Legibly: Daniel J Dewes Train Consist Unit Nun	Employee Releasing Unit for Service Signature: Occupation: Private QMP		
800279	Train Consist Onit Num	ibei (5) – II applicable /		