

Wheel Inspection Report - 4 Axel / 6 Axel

Date: 3/5/20 3002

Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		1 1/4	1 3/16	1 1/4	1/8
2		1 1/8	1 2/8	1 1/8	1/8
3		1 1/2	1 5/16	1 3/16	1/8
4		1 1/4	1 1/8	1 3/16	1/8
5					
6					

Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		1 5/16	1 1/4	1 1/4	1/8
2		1 3/16	1 1/8	1 1/4	1/8
3		1 1/8	1 1/8	1 1/4	1/8
4		1 1/4	1 5/16	1 3/16	1/8
5					
6					