

# Wheel Inspection Report - 4 Axel / 6 Axel

Date: 4/12/20 3003

## Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		22	1 5/16	1 1/4	1/8
2		23	1 3/8	1 5/16	1/8
3		50	1 5/16	1 3/16	1/8
4		49	1 5/16	1 5/16	1/8
5					
6					

## Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		23	1 1/4	1 3/8	1/8
2		25	1 1/8	1 1/4	1/8
3		48	1 5/16	1 3/16	1/8
4		50	1 3/8	1 5/16	1/8
5					
6					