

[REDACTED]

92 Day Locomotive Inspection

Date: 8-8-16

Inspector: J Norton

Loco Init: 6076

Supervisor: C. Talluto

Location: [REDACTED]

Item	Inspected	Repaired	Notes	Item	Inspected	Repaired	Notes
INSPECT RUNNING GEAR	ok			INSPECT AIR FILTERS	ok		
INSPECT CARBODY	ok			BATTERIES/CABLES	ok		could stand some water
INSPECT SAFETY APPL	ok			HEADLIGHTS	ok		all except dim on front end resistor burned out
INSP/LUB HAND BRAKE	ok			AUX. LIGHTS	ok		
INSPECT MAIN GENERATOR	ok		no brushes	TEST HIGH VOLTAGE GROUNDS	ok		
INSPECT AUX GENERATOR	ok		w brushes	TEST LOW VOLTAGE GROUNDS	ok		
INSPECT SLIP RING	ok			TEST WHEEL SLIP	ok		
INSPECT FUEL PUMP	ok		no brushes	TEST GROUND RELAY	ok		
INSPECT ALL CAB HEATERS	ok			INSP FOR WATER LEAKS			Radiator Firmside Bend
#1 TRACTION MTR	ok			INSP FOR FUEL LEAKS	ok		
#2 TRACTION MTR	ok			INSP FOR EXHAUST LEAKS	ok		
#3 TRACTION MTR	ok			TEST AIR GAUGES	ok		
#4 TRACTION MTR	ok		2 brushes	TEST BC LEAKAGE	ok		
COUPLER HT A end			32 3/4	TEST MR LEAKAGE	ok		
COUPLER HT B end			32 1/2	TEST SPEEDOMETER	ok		
PILOT HT A end			4"	SANDERS	ok		
PILOT HT B end			3 3/4"				

Wheel report

	Rim	FL Ht	FL Th		Rim	FL HT	FL Th
Left #1	38	0-5	3-0	Right #1	38	0-5	0-0-0
Left #2	35	0-5 1/2	3-0	Right #2	35	0-5 1/2	3-0
Left #3	38	0-5	5-0	Right #3	39	0-5	3-0
Left #4	35	0-5	2-0	Right #4	35	0-5 1/2	2-0