

Wheel Inspection Report - 4 Axel / 6 Axel

Date: 4/14/20 3001

Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		26	1 1/4	1 5/16	1/8
2		45	1 3/8	1 3/16	1/8
3		33	1 3/8	1 3/16	1/8
4		34	1 3/8	1 5/16	1/8
5					
6					

Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		25	1 5/16	1 3/16	1/8
2		43	1 1/8	1 3/16	1/8
3		32	1 5/16	1 1/4	1/8
4		34	1 1/4	1 1/4	1/8
5					
6					