

# Wheel Inspection Report - 4 Axel / 6 Axel

Date: 6/24/19 4002

## Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		<del>56</del> 58	1 5/16	1 1/16	1/8
2		56	1 1/16	1 7/16	1/8
3		57	1	1 3/8	1/8
4		54	1 1/8	1 7/16	1/8
5		55	1 1/2	1 7/16	1/8
6		56	1 7/16	1 5/16	1/8

## Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		56	1 7/16	1 3/16	1/8
2		56	1 7/16	1 5/16	1/8
3		58	1 9/16	1 1/4	1/8
4		55	1 1/2	1 5/16	1/8
5		57	1 1/2	1 3/8	1/8
6		57	1 1/2	1 5/16	1/8