

Wheel Inspection Report - 4 Axel / 6 Axel

Date: 6/4/20 4003

Left Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		57	1 1/8	1 3/8	1/8
2		54	1 1/8	1 3/8	1/8
3		48	1 1/8	1 3/16	1/8
4		54	1 1/8	1 7/16	1/8
5		45	1 1/4	1 3/16	1/8
6		56	1 5/16	1 3/8	1/8

Right Wheel

#	Defect	Rim Thickness	Flange Thickness	Flange Height	Tread Wear
1		56	1 1/8	1 1/4	1/8
2		56	1 1/2	1 5/16	1/8
3		48	1 7/16	1 1/4	1/8
4		54	1 7/16	1 1/4	1/8
5		45	1 3/8	1 1/4	1/8
6		57	1 3/8	1 3/8	1/8